## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,999,819 B2

Page 1 of 1

APPLICATION NO.: 10/004732

: February 14, 2006

INVENTOR(S)

: John Matthew Swoyer et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Col. 14, Line 52:

"connector ray" should read --connector array--

Signed and Sealed this

Twelfth Day of September, 2006

JON W. DUDAS Director of the United States Patent and Trademark Office